

Before entering SCA

1. Change into scrubs and facility-dedicated shoes
2. Use restroom; remove makeup, jewelry, and extra clothing; tie up hair
3. Clean personal glasses with EPA-registered one-step bactericidal disinfectant cleaner wipe for frames and lens cleaner for lenses
4. Enter the SCA



Outside perimeter line

5. Don face mask with folds down on outside, bend nose bar, pull down under chin; no gaps; beard cover over mask if goatee
6. Don head cover (bouffant cap) over ears *and* hood if full beard, hijab, or other headdress or if hair is not contained by bouffant cap
7. Perform hand hygiene, including a 30-second lather to the elbows, after using nail pick on wet, lathered hands
8. Dry hands with low-lint wipes
9. Don gown (do not put thumb loops in place)
10. Don shoe covers one at a time, stepping over perimeter line



Inside perimeter line

11. Obtain sterile gloves; remove from outer package at empty, clean counter surface
12. Apply alcohol-based hand rub to nails, hands, and wrists
13. When dry, put thumb loops in place and don sterile gloves
14. Sanitize gloves with sterile IPA (unless initial GFT scheduled)

